



荒浜地区堤防復旧工事 進捗状況報告 第10号 (10.1~10.17)




凡例			
済	①舗装版撤去	済	④構造物撤去
済	②裏腹盛土	済	⑤川前盛土
済	③天端盛土		⑥張芝
			⑦法面保護
			⑧敷砂利


1丁目の状況




3, 4丁目の状況



2丁目の状況



5丁目の状況



横断面図

荒浜地区堤防復旧工事 進捗状況報告 第10号(10.1~10.17)

～定点① (No42+6.24) 写真 (荒浜1丁目) 1/2～



～定点① (No42+6.24) 写真 (荒浜1丁目) 2/2～




荒浜地区堤防復旧工事 進捗状況報告 第10号(10.1~10.17)

～定点② (NO32+30) 写真 (荒浜2丁目) 1/2～



~定点② (NO32+30) 写真 (荒浜2丁目) 2/2~



荒浜地区堤防復旧工事 進捗状況報告 第10号(10.1~10.17)

～定点③ (NO30+30) 写真 (荒浜2丁目) 1/2～



~定点③ (NO30+30) 写真 (荒浜2丁目) 2/2~



荒浜地区堤防復旧工事 進捗状況報告 第10号(10.1~10.17)

～定点④ (No23) 写真 (荒浜3丁目) 1/2～



～定点④ (No23) 写真 (荒浜3丁目) 2/2～



荒浜地区堤防復旧工事 進捗状況報告 第10号(10.1~10.17)

～定点⑤(No19)写真 (荒浜4丁目) 1/2～



~定点⑤(No19)写真 (荒浜4丁目) 2/2~



9月11日



9月26日




10月3日



10月16日



～定点⑥ (No13) 写真 (荒浜5丁目)～



～定点⑥ (No13) 写真 (荒浜5丁目)～



荒浜地区堤防復旧工事 進捗状況報告 第10号(10.1~10.16)

～定点⑦ (No0-14) 写真 (荒浜5丁目) 1/2～



～定点⑦ (No0-14) 写真 (荒浜5丁目) 2/2～

